<b>Work Orde</b>	r ID	51343
August 19, 2009	11:41:	38 AM



Page 1

D2582 Accept Item ID: Setup Start **Revision ID:** В Stop Step Leg Assembly **Item Name: Start Qty: 16.00 Start Date:** 08/19/2009 Cust Item ID: Req'd Qty: 16.00 **Required Date: 08/21/2009 Customer:** Reference: Start Run Date: 09-08-19 Tooling: Process Plan: MF Approvals: Date:\_ Stop Date:\_\_\_\_\_ QC: SPC (Y/N): Date: Sequence ID/ Set Up/ Reject Operation Draw Draw Plan Accept Reject Insp. Work Center ID Description Qty Qty Number Rev. Code Number Stamp **Run Hours Draw Nbr Revision Nbr** D2582 Rev B 100 0.00 Small Fab Small Fab 0.00 Memo Assemble as per Dwg D2582 and Small Fab

110 QC QC5- Inspect part completeness to step on  $\ensuremath{W/O}$ 

2) 8 02/08/26

£ \_ \_ \_ \_

Quality Control

Memo

0.00

120 Packaging Identify as per dwg & Stock Location: WB

0.00

3 AV

09-08-24

(Alb) \_\_\_\_\_

Packaging

Memo

0.00

#### Work Order ID 51343

August 19, 2009 11:41:38 AM



Page 2

D2582

**Revision ID:** В Item Name:

Step Leg Assembly

**Start Date:** 

Item ID:

08/19/2009

**Required Date:** 08/21/2009

**Start Qty:** 16.00

Req'd Qty: 16.00



Accept



Run

Setup Start



Start

Stop



Reference:

**Approvals:** 

Process Plan:

**Operation** 

Description

Date:

QC21- Final Inspection - Work Order Release

Date: Tooling:

SPC (Y/N):

Set Up/

0.00

0.00

**Run Hours** 

Draw Number

**Cust Item ID:** 

**Customer:** 

Rev.

Date:

Date:

Draw Plan Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

130

Memo

09/08/26

Quality Control

### Page 1

# **Picklist Print**

August 19, 2009 11:41:38 AM

Work Order ID: 51343

Parent Item:

D2582RevB

Parent Item Name: Step Leg Assembly

Comments:



Start Date: 08/19/2009

**Required Date:** 08/21/2009

**Start Qty: 16.00** 

Required Qty: 16.00

Comments.	,								start Qty. 10.00	,	Required Qty. 1	0.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2278RevF	Manufactured	No			100	Each	34.0000	32.0000	J207	68/24	/	
				<u>Wareho</u>	<u>use</u>	Loc Qty		Loc Code				
				Location								
				Main Wa	arehouse							
				ST			30					
					48090A		0		_	26		
		·		50338		30		_	26			
			Main Wa	arehouse								
			WA		4							
					48090A		4		_			/
D2279RevD		Manufactured	No			100	Each	66.0000	16.0000	<i>Z/S</i>	99/08 <sub>1</sub>	24
				Warehouse		Loc Oty		Loc Code	<u>le</u>			
				Loc	ation							
				Main W	arehouse							
				ST			48	-	_			
					40087		18		_	16		
					44293		18		_			
					47644		12		_			
				Main W								
				WA			18		_			

48090C

18 18

## **Picklist Print**

August 19, 2009 11:41:38 AM

Work Order ID: 51343

Parent Item:

D2582RevB

Parent Item Name: Step Leg Assembly

**Comments:** 



Start Date: 08/19/2009

**Required Date:** 08/21/2009

Page 2

**Start Qty: 16.00** 

Required Oty: 16.00

Comments.								`	<b>2011 (20)</b>		rioquii va Quji	
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2322RevC		Manufactured	No			100	Each	17.0000	16.0000	[[SO]	/08/0	24
Step Spacer				Warehoo	<u>use</u>	Loc	<u>Oty</u>	Loc Code				·
				Loca	<u>ıtion</u>							
				Main Wa	rehouse							
				ST			17			<u>.</u>		
					47644		3		_	<u> </u>		
					48090B		14					/
D3720-1RevA		Manufactured	No			100	Each	29.0000	16.0000	-1		

Step Spacer

Warehouse	Loc Qty	Loc Code	
<b>Location</b>			/
Main Warehouse			
ST	29		
44693	7		
47644	12		
48090	10		

Page 3

### **Picklist Print**

August 19, 2009 11:41:38 AM

Work Order ID: 51343

Parent Item:

D2582RevB

Parent Item Name:

Step Leg Assembly

Comments:



**Start Date:** 08/19/2009

**Required Date:** 08/21/2009

**Start Qty: 16.00** 

Required Qty: 16.00

Comments:							Start Qty: 16.00			Required Qty: 16.00		
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3720-2RevA		Manufactured	No			100	Each	32.0000	16.0000	309	108/24	· · · · ·
			<u>Wareho</u>	use	Loc	<u>Oty</u>	Loc Code					
		,		ation								
				Main Wa	arehouse							
				ST			32		_	# 9		
					44694 47644		9 12			A		
					48090		11			7		
4S20470AD4-4		Purchased	No			100	Each	7,162.000	352.0000	21		
										45 O	108/2	8
Rivet, Universal Head		<del></del>							7	7	/00/~	
*				<u>Wareho</u>	use	Loc	<u>Oty</u>	Loc Code			/	
				Loca	<u>ation</u>						•	
				Main W	arehouse			•				
		-		ST			7162		_	3-1/		
					111359 112314		2162 5000		-	174		
MS20470AD4-5		Purchased	No		112314	100	Each	3,753.000	64.0000	156_	,	,
								•		0/5	0/08/	24
Rivet, Universal Head		184							11111111111	THE	97/01/=	~ /
Tarte, cuit visa rica			Wareho	ouse	<u>Loc</u>	Oty	Loc Code			/ . /		
			Loc	<u>ation</u>				•	•			
٠.				Main W	arehouse				•			
				ST		7	3753					
					.109031		753		_	64		
					111916		3000					

